Figure: 28 TAC §34.1302(b)

6002.152(a)	Branch office registration certificate required	$1,000.00		34.617	Failure to distribute/retain certificate	$500.00
6002.154(a)	No licensed employee	$1000.00		34.618	Installation inspection improperly performed/documented	$50.00-$500.00
6002.154(b)	No license	$3,000.00		34.618	Installation inspection improperly documented	$500.00
6002.154(c)	Licensee not an employee of registered firm	$750.00		34.618	Installation inspection docs not on file for 5 yrs	$500.00
6002.301	Engage in business w/o license or registration certificate	$3,000.00				
	Adopted Standards			34.619(a)	System/modification not planned by authorized person	$3,000.00
34.616(b)(4)	Violation of standards established by 34.607	$50.00-$500.00		34.619(b)	Plans not submitted to AHJ	$500.00
34.6616(b)(4)	Violation of standards established by manufacturers requirements (NFPA 72, §10.3.2)	$50.00-$500.00		34.619(b)	Plans incorrectly submitted to AHJ	$250.00
					Labels	
	Location Business Practices			34.620(a)	Installation label not affixed to inside of control panel cover	$500.00
34.610(a)	Failure to maintain business location	$500.00		34.620(d)	Installation label improperly formatted or incomplete	$500.00
34.610(b)	Designated employee	$500.00		34.620(f)	Installation label incorrectly formatted or incomplete (1 or 2 family)	$500.00
34.610(c)	Registration information not displayed on vehicle	$250.00		34.621(a)	Service label not affixed to control panel cover	$500.00
34.611(f)(2)	Failure to notify SFMO of termination of employee within 14 days	$250.00		34.621(b)	Information about yellow or red label not on service label that corrected the impairments	$500.00
34.616(b)(1)	Installation not performed by or under direct supervision of authorized licensee	$3,000.00		34.623(c) (yellow) 34.624(c) (red)	Owner or AHJ not notified of impairment	$500.00
34.616(b)(1)	Certifying licensee not licensed under ACR of primary registered firm or certifying licensee not present for final acceptance test	$1,000.00		34.621(h)	Service label improperly formatted or incomplete	$500.00
34.616(b)(2)	Licensee attaching label not licensed under ACR of primary registered firm	$1,000.00		34.622(a)	Inspection/test label not filled out in detail or not affixed to inside of control panel cover	$500.00
34.616(b)(2)	Service and maintenance not performed by or under direct supervision of authorized licensee	$3,000.00		34.622(d)	Owner or AHJ not notified of impairment	$500.00
6002.302(a)(3)	Misrepresentation of goods or services	$250.00-$1,000.00		34.622(j)	Inspection/test label incorrectly formatted/incomplete	$500.00
	Monitoring			34.623(a)	Completed yellow label not attached to outside of control panel of impaired system	$500.00
34.616(c)(1)	Monitoring an alarm for an unregistered firm	$3,000.00		34.623(g)	Yellow label incorrectly formatted/incomplete	$500.00
34.616(c)(2)(A)	Connecting an alarm to an unregistered monitoring firm	$2,000.00		34.624(a)	Completed red label not attached to outside of impaired system	$1,000.00
34.616(3)	No licensed technician at central station	$1,000.00		34.624(g)	Red label improperly formatted/incomplete	$500.00

34.613(a)(5)(B)	**Lapse of Insurance**				
Months	Punitive	+	Amount saved		Total
0 - 1	$200	+	$125	=	Warning Letter
1 - 2	$500	+	$250	=	$750
2 - 3	$500	+	$375	=	$875
3 - 4	$500	+	$500	=	$1,000
4 - 5	$500	+	$625	=	$1,125
5 - 6	$500	+	$750	=	$1,250
6 - 7	$750	+	$875	=	$1,625
7 - 8	$750	+	$1,000	=	$1,750
8 - 9	$750	+	$1,125	=	$1,875
9 - 10	$750	+	$1,250	=	$2,000

10 - 11	$750	+	$1,375	=	$2,125
11 - 12	$750	+	$1,500	=	$2,250